

EPA Lead and Copper Rule Revision Required Service Line Inventory Statement:

Ricewood MUD has no lead service lines or galvanized service lines requiring replacement. Ricewood MUD reached this determination because its water distribution system was installed after 1988, the year that Texas implemented the Safe Drinking Water Act banning the use of lead for any public water lines. Additionally, Ricewood MUD has found no evidence of the use of lead service lines (i) in the system records, including distribution system maps and drawings, historical records, meter installation records, inspections and records of the distribution system that indicate the material composition, or (ii) when reading water meters or performing maintenance activities in the course of normal system operations."